



6.0 FIGURES











19-016 Carleton Farms Wells EA Report DE Project# 19-016

FIGURE 5 – FEMA Flood Insurance Rate Map





7.0 APPENDICIES

7.1 APPENDIX A –Field Investigation Photos



Photo 1 - Looking northeast across the vegetative community from proposed Well Pad 1 SW corner.



Photo 2 - Looking north along conservation easement located west of Well Pad 1 from SW corner. EGLE wetland conservation easement on left side of photo.



Photo 3 – Conservation easement sign located west of proposed Well Pad 1.



Photo 4 – Soil pit excavated within proposed Well Pad 1.



Photo 5 – Looking northeast across proposed Well Pad 2 from SW corner.



Photo 6 – Looking east along the small strip of the vegetative community (mowed) within southern portion of Well Pad 2.



Photo 7 - Looking north along the small strip of the vegetative community (mowed) within eastern portion of Well Pad 2.